

CEB Hopper Supports and Grate Supports

Written By: Brianna Kufa



- Angle grinder (1)
- Punch (1)
- Welder (1)
- torch (1)


SUMMARY

Hopper Support ModelGrate Support Model

Additional Materials Required:


3/4"x1.5" Bolts (2)3/4" Nuts (2)Shaker Mount

Step 1 — **Make the Hopper Supports**




- Torch away the necessary areas. See diagrams.
 - The holes for the hopper mounting need to be 28" away from the bottom side. Mark 28" on the opposite tubing walls and torch 1/2" holes. Insure a 1/2" bolt goes all the way thru.
 - Torch the cutaway at the top and the slot.
- Grind away any slag.

Step 2








- Lay one support on the table, with the grate mount slot touching the table.
- Get the Shaker Mount and tighten 3/4" bolts with nuts to the Soil Shaker so the bolt head is where the hammer will be.
- Prop this up on the hopper support, so the first bolt is about 2" above the 28" hole and both bolts are touching the support.
- Mark which side of the shaker you are welding the bolts for.

Step 3



- Tack the bolts in place, remove the nuts and dismount the shaker.
- Protect the threads, and finish welding the bolts to the support.
- You are only doing this on one of the supports, the other side, you will do in place, so the spacing is correct.

Step 4 — **Make the Grate Supports.**



- Punch the hole on the bottom of the supports for each.
- Torch away a 4" section on the top of each grate to make it like the model shown.
 - Remember that the two are mirrored.
 - Cut away the corner so the hopper wont hit it, about a 1" 45 degree triangle.
 - Torch a slot for a 3/4" bolt at the top of the mount, as shown.
- Grind away all the slag.

This document was last generated on 2012-10-31 11:29:54 PM.